UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 7,435,352 B2 Page 1 of 1

APPLICATION NO.: 10/677182
DATED: October 14, 2008
INVENTOR(S): J.-S. Mok et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

<u>COLUMN</u>	<u>LINE</u>	ERROR
12 (Claim 14)	58	before "expose circuit patterns" delete "provide a solder resist pattern"

Signed and Sealed this

Fourth Day of August, 2009

JOHN DOLL
Acting Director of the United States Patent and Trademark Office